

序号	报告编号	发布日期	结论	影像资料
1	GX-B1302/25-7-25010	2025/10/11	所检项目合格。	 A photograph showing industrial machinery, possibly a large valve or pump, with a yellow warning sign that reads "危险区域 请勿靠近" (Dangerous Area, No Approach). The date "2025/09/08" is visible in the bottom right corner of the image.
2	GX-B1302/25-7-25011	2025/10/11	所检项目合格。	 A photograph showing two workers in orange protective suits and hard hats standing in an industrial setting. The date "2025/09/08" is visible in the bottom right corner of the image.

3	GX-B1310/21-7-25207	2025. 10. 13	符合标准要求。			
---	---------------------	--------------	---------	--	---	--