


序号	报告编号	发布日期	结论	影像资料
29	GX-B1328/25-6-25276	2026/1/8	合格。	
30	GX-B1328/25-6-25277	2026/1/8	合格。	

31	GX-B1328/25-6-25278	2026/1/8	合格。		
32	GX-B1328/25-6-25279	2026/1/8	合格。		

33	GX-B1313/21-6-26001~26002	2026/1/15	本次共检电力变压器2台，2台电力变压器所检项目合格。	 A photograph showing a worker in a dark jacket and hood performing maintenance on a large bundle of electrical cables. The worker is holding a tool and looking at a small device. A yellow toolbox is on the ground next to the cables. The background shows a construction site with a crane and a blue sky. The date 2026 01 10 is visible in the bottom right corner of the image.
----	---------------------------	-----------	----------------------------	--