






序号	报告编号	发布日期	结论	影像资料
12	GX-B1343/21-8-26001	2026.1.13	1. 矿井总风量：4294.7 m³/min; 2. 主通风机风量：4348.8 m³/min; 其中-240m中段北巷主通风机2719.8 m³/min, +30m中段南风井主通风机1629.0 m³/min; 3. 矿井有效风量：3612.3 m³/min; 4. 矿井有效风量率：83.1 %; 5. 机站风量：-240m中段北巷主通风机2719.8 m³/min, +30m中段南风井主通风机1629.0 m³/min; 6. 机站风压：-240m中段北巷主通风机1070 Pa, +30m中段南风井主通风机980 Pa; 7. 矿井通风阻力：北风井通风系统1058.1 Pa; 南风井通风系统982.5 Pa。	 iQOO Neo9 Pro 山东省 烟台市 2026.01.08 15:35
13	GX-B1347/21-8-26001	2026.1.13	1、风量（风速）合格率：100%，大于65%，合格； 2、风质合格率：100%，大于90%，合格； 3、作业环境空气质量合格率：100%，大于60%，合格； 4、矿井有效风量率：83.1%，大于60%，合格； 5、风机全压效率：73.7%，大于70%，合格； 6、风量供需比：1.54，符合1.32≤β≤1.67要求，合格； 7、综合指标：92.1%，大于72%，合格。	 iQOO Neo9 Pro 山东省 烟台市 2026.01.08 15:35

14	GX-B1341/24-8-26001	2026.1.13	综合判定：合格。	 A photograph showing two miners in a tunnel. They are wearing blue work clothes, red hard hats with headlamps, and safety harnesses. The miner on the left is holding a clipboard. The background shows the rough rock walls of the tunnel and some equipment. At the bottom of the photo, there is a black bar with white text: 'iQOO Neo9 Pro' on the left and '山东省 烟台市 2026.01.08 14:47' on the right.
15	GX-B1341/24-8-26002	2026.1.13	综合判定：合格。	 A photograph showing two miners in a tunnel, similar to the one above. They are wearing blue work clothes, red hard hats with headlamps, and safety harnesses. The miner on the left is holding a clipboard. The background shows the rough rock walls of the tunnel and some equipment. At the bottom of the photo, there is a black bar with white text: 'iQOO Neo9 Pro' on the left and '山东省 烟台市 2026.01.08 17:06' on the right.

16	GX-B1525/21-8-25055	2026年1月14日	该局部通风机共检5项，除风量、风压不判定外，其他所检项目均合格。	
17	GX-B1525/21-8-25056	2026年1月14日	该局部通风机共检5项，除风量、风压不判定外，其他所检项目均合格。	

18	GX-B1525/21-8-25051	2026年1月14日	该局部通风机共检5项，除风量、风压不判定外，其他所检项目均合格。	
19	GX-B1525/21-8-25052	2026年1月14日	该局部通风机共检5项，除风量、风压不判定外，其他所检项目均合格。	

20	GX-B1525/21-8-25053	2026年1月14日	该局部通风机共检5项，除风量、风压不判定外，其他所检项目均合格。	
21	GX-B1525/21-8-25054	2026年1月14日	该局部通风机共检5项，除风量、风压不判定外，其他所检项目均合格。	

22	GX-B1340/25-8-25066	2026年1月14日	合格。	 <p>施工记录 经 度: 110.181888 纬 度: 39.602353 地 址: 新疆伊犁哈萨克自治州伊宁市 工程名称: 伊宁市供水工程 时 间: 2025-1-14 15:09:46</p>
----	---------------------	------------	-----	---